

# IP Phone Compatibility List (PCL)

This page contains a list of all the SIP devices tested with VoipNow.

- [Overview](#)
- [Supported SIP Devices](#)
  - [Aastra](#)
  - [Alcatel Lucent Enterprise](#)
  - [Cisco](#)
  - [Escene](#)
  - [Fanvil](#)
  - [Grandstream](#)
  - [Linksys](#)
  - [Htek](#)
  - [Panasonic](#)
  - [Polycom](#)
  - [Snom](#)
  - [Spectralink](#)
  - [Thomson](#)
  - [Tiptel](#)
  - [XRS](#)
  - [Yealink](#)
- [Legal Notice](#)

## Overview

Please note that any IP phone implementing SIP standard will work with VoipNow. This is a list of SIP devices and firmware versions that were tested.

These phones can be automatically provisioned using specific configuration files available in VoipNow. **In [this article](#), you'll find hands-on advice on how to create a configuration template for a specific SIP device.**

You may use VoipNow with any other IP phone that supports SIP (Session Initiation Protocol). However, 4PSA will strictly provide full support and provisioning templates for the devices listed below.

New equipment is constantly added to the list.

## Supported SIP Devices

### Aastra

| Model   | Firmware        |
|---------|-----------------|
| 9122i   | 1.4.1 and above |
| 9133i   | 1.4.1 and above |
| 480i    | 1.4.1 and above |
| 480i CT | 1.4.1 and above |
| 51i     | 2.3.x           |

### Alcatel Lucent Enterprise

| Model  | Firmware            |
|--------|---------------------|
| 8018   | 1.52.03.X and above |
| 8068s  | 1.52.03.X and above |
| 8078s  | 1.52.03.X and above |
| M3     | 2.10.16.X and above |
| H2/H2P | 2.10.16.X and above |

### Cisco

| Model | Firmware |
|-------|----------|
|-------|----------|

### Panasonic

| Model    | Firmware |
|----------|----------|
| KX-UT670 | 01.05.x  |
| KX-UT123 | 01.133   |

### Polycom

| Model              | Firmware          |
|--------------------|-------------------|
| IP 501             | 1.6.x/3.1.x       |
| IP 550             | 2.1.x/3.3.x       |
| IP 650             | 3.2.x/3.3.x/4.1.x |
| Soundpoint 300/301 | 1.6.x/3.1.x       |
| Soundpoint 330/320 | 2.1.x/3.3.x       |
| Soundpoint 321/331 | 3.3.x/4.1.x       |
| VVX 3XX            | 5.2.x.x           |

### Snom

| Model | Firmware      |
|-------|---------------|
| 300   | 6.2 and above |

|         |                  |
|---------|------------------|
| 7940    | 7.x/8.x          |
| 7960    | 7.x/8.x          |
| SPA504G | 7.4.x            |
| SPA525G | 7.6.x            |
| 7841    | 10.3.x and above |

## Escene

| Model | Firmware |
|-------|----------|
| ES410 | 2.2.7.x  |
| ES620 | 2.2.7.x  |

## Fanvil

| Model | Firmware |
|-------|----------|
| C62   | 2.2      |
| C56   | 2.2.16.x |
| C400  | 14.0.0.x |
| C600  | 14.0.0.x |
| X2P   | r2.2.0.x |
| X3S   | r2.3.1.x |
| X4    | r2.3.1.x |
| X5S   | R1.0.2   |
| X6    | R1.0.2   |
| PA2   | 2.1.1.x  |

## Grandstream

| Model           | Firmware           |
|-----------------|--------------------|
| Handy Tone 286  | 1.0.8.23 and above |
| Handy Tone 486  | 1.0.8.32 and above |
| Handy Tone 488  | 1.0.3.48 and above |
| Handy Tone 502* | 1.0.3.10 and above |
| GXP-2000        | 1.2.x.x            |
| GXP-2020        | 1.2.x.x            |

## Linksys

| Model   | Firmware         |
|---------|------------------|
| SPA-122 | 1.3.5            |
| SPA-901 | 4.1.11 and above |
| SPA-921 | 4.1.10 and above |
| SPA-922 | 4.1.10 and above |
| SPA-941 | 4.1.10 and above |

|     |                     |
|-----|---------------------|
| 320 | 6.2 and above       |
| 360 | 6.2 and above       |
| M3  | 2.x and above       |
| 785 | 10.1.5.x and above  |
| 765 | 8.9.3.x and above   |
| 715 | 8.9.x and above     |
| 120 | 10.1.10.x and above |

## Spectralink

| Model            | Firmware |
|------------------|----------|
| Spectralink 8440 | 4.6.x    |

## Thomson

| Model   | Firmware |
|---------|----------|
| ST2030S | 1.6.x    |

## Tiptel

| Model | Firmware |
|-------|----------|
| IP280 | 6.x.x.x  |
| IP284 | 6.x.x.x  |
| IP286 | 6.x.x.x  |

## XRS

| Model | Firmware |
|-------|----------|
| 5440  | 2.2.7    |

## Yealink

| Model    | Firmware         |
|----------|------------------|
| SIP-T19P | 31.72.X.X        |
| SIP-T20P | 6.x.x.x/7.70.x.x |
| SIP-T22P | 6.x.x.x/7.70.x.x |
| SIP-T26P | 6.x.x.x/7.70.x.x |
| SIP-T28P | 6.x.x.x/7.70.x.x |
| SIP-T41P | 36.72.X.X        |
| SIP-T46G | 28.72.X.X        |
| SIP-W52P | 25.40.X.X        |
| SIP-T41S | 66.82.x.x        |
| SIP-T42S | 66.82.x.x        |
| SIP-T46S | 66.82.x.x        |
| SIP-T48S | 66.82.x.x        |

|         |                  |
|---------|------------------|
| SPA-942 | 4.1.10 and above |
| SPA-962 | 4.1.10 and above |
| PAP-2T  | 5.1.x and above  |
| SPA2102 | 5.2.x and above  |
| SPA8000 | 5.1.x and above  |

## Htek

| Model  | Firmware            |
|--------|---------------------|
| UC902  | 2.0.4.2.x and above |
| UC924P | 2.0.3.x and above   |

## Legal Notice

This content is provided to the maximum extent permitted by applicable law. It does not imply warranties and merchant-ability, or anything exceeding their fitness for a particular purpose. 4PSA shall not be liable for any damages caused or in connection with the use of this content, including direct, indirect and consequential damages, loss of profits or special damages.

This list shall be periodically updated without notice.